ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	2	Chowdeshwari Ward
Street ID	**Street Name**	**Significant Landmark**
W0380, W0385	9th Crs Lakshmi Sagar Lyt, 8th Crs Gramatana	SWD Drain near Easwarappa house Kamakshamma Layout
Segment No.	**Total Length (m)**	
2/C-W0380/S011554	37.97	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	37.97	77.591762	13.104988	77.592112	13.104975	W0385	RAILWAY BOUNDARY

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing CC Covering to Existing SWD Drain near Easwarappa house Kamakshamma Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	1000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	SWD DRAIN
Tender	**Work Details**	**Job No. / Work Code**
Tender	Providing CC Covering to Existing SWD Drain near Easwarappa house Kamakshamma Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-15-000017
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D) E-PMT-04/WO/69/2014-15	28/01/2015	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2015	29/04/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
LINGRAJU		0.00
Phone No.	**E-Mail ID**	

ld Inspection Details

Number of Trees	Any Other Information	Name
2		RAMASANJEEVAIAH
Date of Inspection	**Remarks**	
29/01/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	29/01/2017	28/02/2017	COMPLETED
SE	VASU K M	29/01/2017	28/02/2017	COMPLETED
EE	SRINIVAS	29/01/2017	28/02/2017	COMPLETED
AEE	G.B. PRABHAKAR	29/01/2017	28/02/2017	COMPLETED
AE	RAMASANJEEVAIAH	29/01/2017	28/02/2017	COMPLETED
AE	RAMASANJEEVAIAH	29/01/2017	28/02/2017	COMPLETED